

**TABLE OF OBSERVED FEATURES
 SURVEY AREA 5
 PROFILE HOUSE BRANCH
 MUCHMORE ROAD, BETHLEHEM TO
 US ROUTE 3, BETHLEHEM**

Feature Name	Mile Post	Town	NR	Photo No. (s)	Date	Notes
ROW/Profile Recreational Trail start at Muchmore Rd.	*	Bethlehem	N/C	1	?	ROW is mowed grass trail with no evidence of railroad resources for 1400' to Trudeau Rd. crossing. *Mileposts unknown.
ROW/Profile Recreational Trail crossing Trudeau Rd.	*	Bethlehem	N/C	2	?	Grassed trail.
Bridge No. 222a over unnamed stream	*	Bethlehem	C	3	?	Wood stringer on split fieldstone abutments, 3' span. ~500' south of Trudeau Rd.
ROW	*	Bethlehem	N/C	4	?	Character of ROW ~ 2700' south of Trudeau Rd.
Bridge No. 222b over unnamed stream	*	Bethlehem	N/C	5	?	Rebuilt wood stringer on split fieldstone abutments, ~4' span. ~2750' south of Trudeau Rd. Lack of integrity.
Bridge No. 222c over unnamed stream	*	Bethlehem	N/C	6	?	Rebuilt wood stringer on split fieldstone abutments, ~5' span. . ~3100' south of Trudeau Rd. Lack of integrity.
Bridge No. 222 over unnamed stream	*	Bethlehem	N/C	7	?	Rebuilt wood stringer on rebuilt split fieldstone abutments, ~8' span. . ~3350' south of Trudeau Rd. Integrity compromised.
ROW	*	Bethlehem	C	8	?	Character of ROW ~7500' south of Trudeau Rd. Straight, level, substantially raised railbed makes this identifiable as a railbed to most observers.
Beaver Brook Bridge, Profile Recreational Trail	*	Bethlehem	N/C	9	?	New trail bridge.
ROW	*	Bethlehem	N/C	10	?	Character of ROW 700' north of US 3.
ROW crossing US 3	*	Bethlehem	N/C	11	?	No evidence of railroad resources.



PHOTO KEY: Survey Area 5, Map 1. Pierce Bridge to US 3 Bethlehem.

**PHOTOGRAPHS
SURVEY AREA 5
PROFILE HOUSE BRANCH
MUCHMORE ROAD, BETHLEHEM TO
US ROUTE 3, BETHLEHEM**



Photo # 1 description: Entrance to ROW/ Profile Recreational Trail off Muchmore Road, Bethlehem, west of Pierce Bridge. No evidence of ROW or resources between this point and the main line on north side of Ammonoosuc R. NOTE: Mile points are unknown.

Photo ID #: S5_1444 Direction: S Date: 7/18/2019 Image stored at: HDC



Photo # 2 description: Entrance to ROW/Trail off Trudeau Road, Bethlehem. No ROW resources are located on the 1400' section between Muchmore Rd and Trudeau Rd.

Photo ID #: S5_1445 Direction: S Date: 7/18/2019 Image stored at: HDC



Photo # 3 description: B&M Bridge 222a, Bethlehem. 500' south of Trudeau Rd. crossing. Wood stringer on split fieldstone abutments, ~ 3' span. nd.

Photo ID #: S5_1446 Direction: W Date: 7/18/2019 Image stored at: HDC



Photo # 4 description: Character of ROW 2700' south of Trudeau Rd. crossing, Bethlehem. Junction with private trail running east-west.

Photo ID #: S5_1448 Direction: S Date: 7/18/2019 Image stored at: HDC



Photo # 5 description: B&M Bridge 222b, Bethlehem. 2750' south of Trudeau Rd. crossing. Wood stringer (recently rebuilt) on split fieldstone abutments, ~4' span. nd.

Photo ID #: S5_1449 Direction: W Date: 7/18/2019 Image stored at: HDC



Photo # 6 description: B&M Bridge 222c, Bethlehem. 3100' south of Trudeau Rd. crossing. Wood stringer (recently rebuilt) on split fieldstone abutments, ~5' span. nd.

Photo ID #: S5_1451 Direction: W Date: 7/18/2019 Image stored at: HDC



Photo # 7 description: B&M Bridge 222, Bethlehem. 3350' south of Trudeau Rd. crossing. Wood stringer (recently rebuilt) on rebuilt split fieldstone abutments, ~8' span. nd.

Photo ID #: S5_1453 Direction: W Date: 7/18/2019 Image stored at: HDC



Photo # 8 description: Character of ROW 7500' south of Trudeau Rd. crossing, Bethlehem. 50' north of Beaver Brook bridge. Location of Beaver Brook overflow; consisting of two new 48" CMP culverts.

Photo ID #: S5_1454 Direction: S Date: 7/18/2019 Image stored at: HDC



Photo # 9 description: Beaver Brook Bridge, Profile Recreational Trail, Bethlehem. Newly constructed trail bridge on new stone abutments; probably utilized some split fieldstone from previous bridge.

Photo ID #: S5_1455 Direction: S Date: 7/18/2019 Image stored at: HDC



Photo # 10 description: Character of ROW 700' north of US 3, Bethlehem. Junction with Gale River Trail running east-west. Note trail sign at left. ROW continues south but impassable.

Photo ID #: S5_1456 Direction: N Date: 7/18/2019 Image stored at: HDC



Photo # 11 description: Location of former ROW crossing US 3 at entrance to Gale River Loop Road in White Mtn. National Forest, Bethlehem. ROW then curves west and follows US 3 which was built on the ROW to Profile House, Franconia. No evidence of ROW remains south of this point.

Photo ID #: S5_1462 Direction: S Date: 7/18/2019 Image stored at: HDC